

H m.	f cm.	c cm.	H' m.	S mq.
4.60	125	70	4.69	4.573
4.65	125	↑	4.74	4.622
4.70	130	↑	4.79	4.790
4.75	↑	↑	4.84	4.840
4.80	↑	↑	4.90	4.900
4.85	↑	↑	4.95	4.950
4.90	↓	↑	5.00	5.000
4.95	130	↑	5.05	5.050
5.00	135	↑	5.10	5.228
5.05	↑	↑	5.15	5.279
5.10	↑	↑	5.20	5.330
5.15	↑	↑	5.25	5.381
5.20	↓	↑	5.30	5.433
5.25	135	↑	5.35	5.484
5.30	140	↑	5.41	5.681
5.35	↑	↑	5.46	5.733
5.40	↑	↓	5.51	5.786
5.45	↓	70	5.56	5.838
5.50	140	75	5.61	6.031
5.55	145	↑	5.66	6.226
5.60	↑	↑	5.71	6.281
5.65	↑	↑	5.76	6.336
5.70	↓	↓	5.81	6.391
5.75	145	75	5.86	6.446

H m.	f cm.	c cm.	H' m.	S mq.
5.80	145	75	5.92	6.512
5.85	150	↑	5.97	6.716
5.90	↑	↑	6.02	6.773
5.95	↑	↑	6.07	6.829
6.00	↑	↑	6.12	6.885
6.05	↓	↑	6.17	6.941
6.10	150	↑	6.22	6.998
6.15	155	↑	6.27	7.211
6.20	↑	↑	6.32	7.268
6.25	↑	↑	6.37	7.326
6.30	↑	↑	6.43	7.395
6.35	↓	↑	6.48	7.452
6.40	155	↓	6.53	7.510
6.45	160	75	6.58	7.732
6.50	↑	80	6.63	7.956
6.55	↑	↑	6.68	8.016
6.60	↑	↑	6.73	8.076
6.65	↓	↑	6.78	8.136
6.70	160	↑	6.83	8.196
6.75	165	↑	6.88	8.428
6.80	↑	↑	6.94	8.502
6.85	↑	↑	6.99	8.563
6.90	↓	↓	7.04	8.624
6.95	165	80	7.09	8.685